

HOS 247

ELD Logbook To Rely On

Certificate of Compliance

Electronic Logging Device - ELD



The HOS247 ELD is compliant with Federal Motor Carrier Safety Regulation 49 CFR § 385, 386, 390, and 395 regarding Electronic Logging Devices. HOS247 has been approved by the FMCSA as certified ELD vendor.



The HOS247 ELD is compliant with Section 83 of the Commercial Vehicle Drivers Hours of Service Regulations regarding the use of electronic recording devices.

www.hos247.com

Contact the support team at 415-839-9977 or team@hos247.com

DOT Inspection Mode

Let an authorized safety official inspect your logs



- ✓ Tap “DOT Inspection” in the menu & press “Start Inspection”. Let an officer to view your logs directly from your mobile device. Show this instruction card if requested.
- ✓ An inspector may press arrows to view previous or next day’s logs.
- ✓ An inspector may view the log form, the log graph and the log events with notes.
- ✓ Exit the inspection mode by pressing back arrow in the left top corner of the app.

Send Logs

HOS247 ELD is capable of producing and transferring the ELD records via telematics transfer methods. In order to send the ELD records, press “DOT Inspection” menu item, then press “Send Logs” button, add “Comment” if provided by an authorized safety official, select “Data Transfer Type” (Email or Web Services) and press “Send” to transfer the ELD records.

www.hos247.com

Contact the support team at 415-839-9977 or team@hos247.com

Malfunction Manual

in accordance with the guidelines set forth in 395.34



Malfunction indication

Immediately contact the support if LED light on the device is off when the device is plugged into the diagnostic port or if the malfunction reported by the app.



Note the malfunction

Note the malfunction and provide a written notice to your fleet within 24 hours.



Switch to paper logs

Keep a paper log for that day and until the device is repaired or replaced. In the event of an inspection, display the previous 7 days from the app.



8 days rule

In the event of an ELD malfunction, the motor carrier must take actions to correct the malfunction within 8 days of discovery.

www.hos247.com

Contact the support team at 415-839-9977 or team@hos247.com